IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Applicant:

J.R. Webb

Attorney Docket No.: 132880

Patent No.:

US 7,262,563 B2

Application No.: 10/707314

Issued:

August 28, 2007

Filing Date: December 4, 2003

Confirmation No.: 1313

Title:

METHOD AND APPARATUS FOR PROVIDING A DYNAMIC ROTATIONAL

ALIGNMENT OF A CATHODE RAY TUBE RASTER

REQUEST FOR CERTIFICATE OF CORRECTION

Seattle, Washington 98101

ATTN:

CERTIFICATE OF CORRECTION BRANCH

COMMISSIONER FOR PATENTS:

Enclosed is a Certificate of Correction, Form PTO-1050, for the above-identified U.S. Letters Patent. The errors in the printed patent listed on the enclosed form occurred at the corresponding locations in the application file listed below:

Column,	Line	Page,	Line
9 (Claim 1,	35 line 5)		
9 (Claim 1,	40		
9	42		
(Claim 1, 10 (Claim 2,	line 12) 2 line 2)		
10 (Claim 2,	3 line 3)		
10	7		

Column,	Line	Page,	Line
(Claim 3,	line 2)		
10 (Claim 3,	7		
10 (Claim 3,	8 line 3)		
10 (Claim 3,	9 line 4)		
10 (Claim 4,	11 line 1)		
10 (Claim 5,	27 line 14)		
10 (Claim 6,	29 line 2)		
10 (Claim 6,	30 line 3)		
10 (Claim 6,	30 line 3)		
10 (Claim 7,	34 line 2)		
10 (Claim 7,	34 line 2)		
10 (Claim 7,	35 line 3)		
10 (Claim 7,	36 line 4)		
10 (Claim 8,	38 line 1)		

LAW OFFICES OF
CHRISTENSEN O'CONNOR JOHNSON KINDNESSPLLC
1420 Fifth Avenue
Suite 2800
Seattle, Washington 98101
206.682.8100

The \$100 fee under 37 C.F.R. § 2.6(a)(9) is to be charged to a credit card. The Commissioner is hereby authorized to charge any other fees associated with this paper, or credit any overpayment, to Deposit Account No. 03-1740.

Respectfully submitted,

CHRISTENSEN O'CONNOR JOHNSON KINDNESSPLLC

David P. Sheldon

Registration No. 62,494

Direct Dial No. 206.695.1611

DPS:lal

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

Page 1 of 5

PATENT NO.

US 7,262,536 B2

APPLICATION NO. :

10/707,314

ISSUE DATE

August 28, 2007

INVENTOR(S)

J.R. Webb

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN	LINE	<u>ERROR</u>
9	35	"adding the first correction magnetic flux" should read
(Claim 1,	line 5)	adding the first correction magnetic flux component
9	40	"adding the second correction magnetic flux" should
(Claim 1,	line 10)	readadding the second correction magnetic flux component
9	42	"wherein the resultant magnetic flux is a substantially"
(Claim 1,	line 12)	should readwherein the resultant magnetic flux is substantially
10	2	"wherein the first correction magnetic flux" should
(Claim 2,	line 2)	readwherein the first correction magnetic flux component

MAILING ADDRESS OF SENDER (Please do not use customer number below):

Christensen O'Connor Johnson Kindness^{PLLC} 1420 Fifth Avenue, Suite 2800 Seattle, WA 98101

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number

(Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

Page 2 of 5

PATENT NO.

US 7,262,536 B2

APPLICATION NO. :

10/707,314

ISSUE DATE

August 28, 2007

INVENTOR(S)

J.R. Webb

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUM	MN LINE	ERROR
10	3	"the second correction magnetic flux" should read the
(Claim	2, line 3)	second correction magnetic flux component
10	7	"wherein the first correction magnetic flux" should
(Claim	3, line 2)	readwherein the first correction magnetic flux component
10	7	"during a first scan and wherein" should readduring a first scan, wherein
(Claim	3, line 2)	
10	8	"wherein the second correction magnetic flux" should
(Claim	3, line 3)	readwherein the second correction magnetic flux component

MAILING ADDRESS OF SENDER (Please do not use customer number below):

Christensen O'Connor Johnson Kindness^{PLLC} 1420 Fifth Avenue, Suite 2800 Seattle, WA 98101

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

Page 3 of 5

PATENT NO.

US 7,262,536 B2

APPLICATION NO. :

10/707,314

ISSUE DATE

August 28, 2007

INVENTOR(S)

J.R. Webb

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

	COLUMN	LINE	ERROR
	10	9	"during a second scan wherein" should readduring a
	(Claim 3,	line 4)	second scan, and wherein
	10	11	"wherein the resultant magnetic flux" should read
	(Claim 4,	line 1)	wherein the resultant vertical deflection magnetic flux
	10	27	"a substantially free" should readsubstantially free
	(Claim 5,	line 14)	
,	10	29	"wherein the first correction magnetic flux" should
	(Claim 6,	line 2)	readwherein the first correction magnetic flux component

MAILING ADDRESS OF SENDER (Please do not use customer number below):

Christensen O'Connor Johnson Kindness^{PLLC} 1420 Fifth Avenue, Suite 2800 Seattle, WA 98101

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number
(Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

Page 4 of 5

PATENT NO.

US 7,262,536 B2

APPLICATION NO. :

10/707.314

ISSUE DATE

August 28, 2007

INVENTOR(S)

J.R. Webb

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

<u>COLUMN</u>	LINE	ERROR
10	30	"the second correction magnetic flux" should readthe
(Claim 6,	line 3)	second correction magnetic flux component
10	30	"a first correction magnetic magnitude" should reada first correction magnetic flux magnitude
(Claim 6,	line 3)	
10	34	"wherein the first correction magnetic flux" should readwherein the first correction magnetic flux component
(Claim 7,	line 2)	
10	34	"during a first scan and wherein" should readduring a first scan, wherein
(Claim 7,	line 2)	

MAILING ADDRESS OF SENDER (Please do not use customer number below):

Christensen O'Connor Johnson Kindness^{PLLC} 1420 Fifth Avenue, Suite 2800 Seattle, WA 98101

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number

(Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

Page 5 of 5

PATENT NO.

US 7,262,536 B2

APPLICATION NO. :

10/707.314

ISSUE DATE

August 28, 2007

INVENTOR(S)

J.R. Webb

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLU	<u>IMN</u>	<u>LINE</u>	ERROR
10)	35	"wherein the second correction magnetic flux" should readwherein the second correction magnetic flux
(Clair	n 7,	line 3)	component
10	•	36	"added during a second scan wherein" should readadded during a second scan, and wherein
(Clair	n 7,	line 4)	added during a second sean, and wherein
10)	38	"wherein the resultant magnetic flux" should readwherein the resultant vertical deflection magnetic
(Clain	n 8,	line 1)	flux

MAILING ADDRESS OF SENDER (Please do not use customer number below):

Christensen O'Connor Johnson Kindness^{PLLC} 1420 Fifth Avenue, Suite 2800 Seattle, WA 98101